Revised 12/04

CORRES. CONTROL INCOMING LTR NO.

00014 RFUS

DUE DATE



RECEIVED

2005 JAN 12 P 4:Department of Energy

CORRESPONDE ROCKY FLATS PROJECT OFFICE CONTROL 10808 HIGHWAY 93, UNIT A GOLDEN, COLORADO 80403-8200

DEC 2 3 2004

04-DOE-00965

DIST.	LTR	EΝ
BERARDINI, J.H.	X	
BOGNAR, E.S.	X	
BROOKS I	X	
CARPENTER, M. CIUCCI, J.A.	X	
CIUCCI, J.A.		
CROCKETT, G. A.		
DECK, C. A.	X	
DEGENHART, K, R.	X	
DEL VECCHIO, D.		
DIETER, T. J.		
FFRRFRA D W	X	
GIACOMINI, J. J.		
LINDSAY, D. C.		
LONG, J. W.		
LYLE, J. L.		
MARTINEZ, L. A.	X	
NAGEL, R. E. NESTA, S.	X	
NESTA, S.	X	
NORTH, K.	X	
SHELTON, D. C.	X	
SPEARS, M. S.	X	
TUOR, N. R.	X	
WIEMELT, K. WILLIAMS, J. L.	X	
WILLIAMS, J. L.		\Box
ZAHM, C.	X	
Gibbs, F	$\boldsymbol{\chi}$	
7		
F055 D	\mathcal{X}	
,		

COR. CONTROL X
ADMIN. RECORD X
PATS/130

Reviewed for Addressee Corres. Control RFP

Ulajos Sc Date By

Ref. Ltr. #

DOE ORDER # 5400.1

Mr. Steven H. Gunderson Rocky Flats Cleanup Agreement Project Coordinator Colorado Department of Public Health and Environment 4300 Cherry Creek Drive South Denver, Colorado 80246-1530

Dear Mr. Gunderson:

In accordance with the Rocky Flats Cleanup Agreement Standard Operating Protocol (RSOP) for Facility Disposition, this letter and its enclosures is notification for RSOP implementation. This notification is for all activities required to demolish and disposition Building 528. This Decontamination and Decommissioning activity will utilize a combined RSOP strategy for demolition:

- The portions of the building that meet unrestricted release will be demolished in accordance with the RSOP for Facility Disposition. See attached building demolition description and conditions.
- The portions of the building that do not meet unrestricted release will be removed in accordance with the RSOP for Component Removal, Size Reduction, and Decontamination Activities, Section 3.8. (Included is the six point analysis)
- This notification does not include the slab for Building 883. The slab will remain in place and protected until the entire building has been demolished; the slab will be removed in accordance the RSOP for Environmental Remediation, Notification (in preparation).

The Reconnaissance Level Characterization Report for Building 528 was submitted to the Colorado Department of Health and Environment, and received official concurrence on March 25, 2002. Building 528 has been determined to be a Type 2 facility due to failure to meet the unrestricted release criteria prior to application of a fixative. A fixative has been applied to the remaining contamination in the building. Building demolition debris will be dispositioned as low-level waste. The Pre-determined Survey Report was signed out on December 21, 2004.

This work will be conducted by Kaiser-Hill Company, L.L.C (K-H). The requirements, methods, controls, and processes outlined in the RSOP will be followed. This work will be conducted in accordance with the work control documentation prepared by K-H and its subcontractor. The exact methods and process and progress of the activities will be



ADMIN RECORD

B559-A-000035

Mr. Steven H. Gunderson 04-DOE-00965

2

communicated to Department of Energy/Lead Regulatory Agencies through the consultative process. A schedule for this work is enclosed.

Questions may be directed to Gary P. Morgan, Rocky Flats Project Office, at (303) 966-6003.

Sincerely,

Joseph A. Legare

Director of Project Management

Enclosure

cc w/o Encl.:

F. Gibbs, K-H RISS

S. Nesta, K-H RISS D&D

D. Foss, K-H RISS D&D

M. Aguilar, USEPA

cc w/ Encl.:

Administrative Record

2/2